Fax : (0522)-2452581

Telephone: (0522)-2465715 Telegram: 'RAILMANAK', Luckno

Telegram: 'RAILMANAK', Lucknow Email: dell7@rdso.railnet.gov.in



भारत सरकार — रेल मंत्रालय अनुसंधान अभिकल्प और मानक संगठन लखनऊ — 226011

Government of India - Ministry of Railways Research, Designs & Standards Organization, LUCKNOW - 226011

No. EL/11.5.5/2 Date: 15.12.2009

Chief Electrical Engineers,

- East Central Railway, Hazipur 844 101 (Bihar)
- South East Central Railway, Bilaspur-495 004.
- West Central Railway, Opp. Indira Market, Jabalpur-482001
- ➤ Northern Railway, Baroda House, New Delhi-110 001.
- ➤ Central Railway, 2nd floor, Parcel Office Bldg., Mumbai CST-400 001
- South Central Railway, Rail Nilyam, Secunderabad 500 071.
- Chittaranjan Locomotive Works, Chittaranjan-713 331 (WB)

MODIFICATION SHEET NO. RDSO/2009/EL/MS/0385 (Rev.0), Dated 15.12.2009

1.0 Title:

Partial blocking of opening duct of back side of auxiliary converter of three phase electric locomotives.

2.0 Object:

Railways have been reporting problem of dust accumulation inside the machine room chamber and on the electronic cards of three phase electric locomotives. This is a major problem, which affects reliability of electronic cards. The problem of dust accumulation is attributed to less pressurization in machine room and improper filtering of incoming air to machine room. In the existing system, the air delivery of the machine room blowers first passes through the heat sink of electronic cubicle of power converter, auxiliary converter, vehicle control unit; and WRE & GG modules of auxiliary converter and thereafter it goes to machine room compartment. There are four ventilators in WAP5 locomotive and six in WAG9/WAP7 locomotive for escaping out the machine room air.

RDSO conducted the measurement of air flow at the various locations of duct outlet in MRB-1 circuit (fig-1) by removing traction converter, auxiliary converter and vehicle control unit in one imported locomotive (loco no. 31015) at Electric Loco Shed, GMO and in one new loco at CLW. The measurements are summarized in table-1




Fig-1

SN	Loco no.	MRB-1	SCMRB-1	Air flow in meter/second						
				BUR front duct				BUR back duct		
				L-1	L-2	R-1	R-2	L	R	
01	31015 (Imported Loco)	SH	Landert	6.5	2.0	5.8	10	1.2	3.0	
02	TPP-63 (CLW Loco)	SH	SH	5.1	0.1/2.0	5.8	2.4	4.5	10.8	

Table-1

It can be seen from the above table that there is a variation in air velocity in CLW built locomotive as compared to imported locomotive.

One of the reason attributed for this in CLW built locomotive is "the duct opening of back side of auxiliary converter which was found to be blocked around 75% in imported loco where as in CLW built loco this was 100% open (fig-2 & 3)."

Blocked around 75% in imported locos



Fig-2: Imported loco

100% open in CLW built locos



Fig-3: CLW loco

The modification shown in fig-2 was done by ABB vide modification release no. 431 rev A dated 26.11.2000 (copy enclosed) on all imported WAG9 and WAP5 loco to improve front side cooling of power modules of auxiliary converter. This modification has not been implemented by CLW in indigenously built three phase locomotives.

Thus in order to improve the front side cooling of power modules of auxiliary converter, the modification as per ABB vide modification release no. 431 rev A dated 26.11.2000 (copy enclosed) is required to be done at the earliest.

3.0 Existing Arrangement:

The duct opening of back side of auxiliary converter is found 100% open in CLW built WAP-7 & WAG-9 locomotives.

4.0 Modified Arrangement:

Duct opening of back side of Auxiliary Converter has to be blocked 75% in place of 100% open with MS plate of 2 mm thickness of proper and required size.

5.0 Application to class of locomotives: WAP-5, WAP-7, WAG-9, WAG-9H.

5.0 Material Required:

MS plate of 2 mm thickness of required size.

7.0 Material Rendered Surplus:

Nil.

8.0 Reference:

Nil

9.0 Modification Drawing:

Attached.

10.0 Agency of Implementation:

CLW and Loco Sheds holding WAP-5, WAP-7, Wag-9 & WAG-9H locomotives.

(Sandeep Srivastava) for Director General/Elect.

Encl: As above.

Copy to:-

- 1. Secretary (Electric Traction), Railway Board, Rail Bhavan, New Delhi-110 001
- 2. Sr. DEE (TRS), Electric Loco Sheds,
 - Central Railway, Ajni (Nagpur)-440008.
 - South East Central Railway, BMY Complex, Bhilai, Durg-490 025.
 - Western Railway, Tughlakabad, New Delhi-110 044.
 - Northern Railway, Ghaziabad (UP)-201 001.
 - East Central Railway, Gomoh-828 401
 - South Central Railway, Lalaguda, Secunderabad 500 017.

(Sandeep Srivastava) for Director General/Elect.

Encl: As above

Modification Release **Daimler Chrysler Railsystems** Rev.: ADtranz (Switzerland) Ltd. 431 Date: Modification Release 26.11.2000 Project: Issued by: Order No.: Harald Hack / BLSA Indian Railways / IR-GP140 F361250 Subject: Auxiliary converter air cooling Concerned: Implement on Loco-No.: Account No.: X WAP5 30000 - 30010 (all fleet) X WAG9 31000 - 31021 (all fleet) Problem description:

Air flow measurements on the locomotives have shown, that the cooling air flow through the heat exchangers on the auxiliary converter modules is not proper maintained.

Remedial Measures:


In order to increase the air speed through the heat exchangers, additional deflectors have to be installed on the auxiliary converter covers.


Documents concerned:


Type of document	Document No.	Revision	Title	
drawing	MR431_01.vsd	-	BUR Air deflector electronics, type 1	
drawing	MR431_02.vsd	8.00	BUR Air deflector electronics, type 2	
drawing	MR431_03.vsd	2042	Air deflector for auxiliary converter, type 3	
drawing	MR431_04.vsd	-	Air deflector for auxiliary converter, type 4	
drawing	MR431_05.vsd	-	BUR Air deflector electronics, types 1 & 2	
drawing	MR431_05.vsd	928	BUR Air deflector arrangement	
drawing	Defl_el.doc	-	BUR Air deflector (electronics), rear side of BUR Box	


Distribution:


Company / Location	Responsible	Copies	Incl. Documents

















. Bautze /DEFL_EL.DOC