Fax : (0522)-2452581 Telephone: (0522)-2465715

Telegram: 'RAILMANAK', Lucknow Email: dsetplgroup@gmail.com



भारत सरकार — रेल मंत्रालय अनुसंघान अभिकल्प और मानक संगठन लखनऊ — 226011

Government of India - Ministry of Railways Research, Designs & Standards Organization, LUCKNOW - 226011

No. EL/11.5.5/4

Dated: 01.07.2014.

Chief Electrical Engineers,

- ➤ Central Railway, 2nd floor, Parcel Office Bldg., Mumbai CST-400 001
- East Central Railway, Hazipur 844 101 (Bihar)
- Eastern Railway, Fairlie Place, Kolkata -700 001
- ➤ East Coast Railway, Railway Complex, Bhuvneshwar 751 023
- North Central Railway, Allahabad 211 001
- Northern Railway, Baroda House, New Delhi-110 001.
- North Eastern Railway, Gorakhpur 273 001
- South Central Railway, Rail Nilyam, Secunderabad 500 071.
- South East Central Railway, Bilaspur-495 004.
- South Eastern Railway, Garden Reach, Kolkata-700 043
- Southern Railway, Park Town, Chennai-600 003
- West Central Railway, Jabalpur 482 001.
- Western Railway, Churchgate, Mumbai –400 020

MODIFICATION SHEET NO. RDSO/2014/EL/MS/ 435, Rev. '0' Dated 06.06.2014

1.0 **Title**:

Modification sheet to avoid necessity of cab changing in case of failure of processor cards of VCU of three phase locomotive (WAP7).

2.0 Object:

Presently, in three phase locomotives provided with Vehicle Control Units based on MICAS-S2 communication protocol between different bus stations, it is not possible to have redundancy among VCU-1 and VCU-2 in case STB/HBB processors failure and cab changing is needed in some cases by driver to clear the section. However in TCN based VCU, this feature has successfully been implemented by M/s BHEL. Based on the experience gained, new wiring required for modification in locomotives provided with MICAS based VCUs was finalized by RDSO in association with CLW and MS-429 was issued to avoid necessity of cab changing in WAG9/WAG9H locomotives. Further similar modification has been implemented in one WAP7 locomotive (30381) by CLW. Based on above, this MS for WAP7 locomotives has been prepared to implement in all MICAS- S2 VCU based WAP7 locomotives.

- 3.0 **Existing Arrangement with cross-references of respective design document:**The existing arrangement of wiring for the input/output signals with related processors is given in Annexure-I for WAP7 locomotive with green colour.
- 4.0 **Modified Arrangement to replace existing arrangement as given above in 3.0:** The modified arrangement of wiring for the input/output signals with related processors for WAP7 is given in Annexure-I with red colour along with wiring details.
- 5.0 **Redundancy Status after modification:** The failed functions and other details after implementing the modification shall be as per Annexure-II.
- 6.0 **Trouble shooting directory for driver shall be modified as:** The existing content and modified content in TSD shall be as per Annexure-III.
- 7.0 The modified software to be down loaded in VCU1/VCU2 processors shall be issued to Electric Loco Sheds by CLW for modifications in existing locomotives.

8.0 Application to class of locomotives:

WAP-7 locomotives fitted with VCUs based on MICAS-S2 Communication Protocol.

9.0 Material Required:

- (i) 0.5 sq.mm cable (as per CLW specification no. CLW/ES/3/0458 Alt.E) of approximately 60 m length and 1.5 sq.mm cable (as per CLW specification no. CLW/ES/3/0458 Alt.E) of approximately 50 m length per locomotive.
- (ii) 6 Wago connector with 2 terminals per locomotive.

10.0 Material Rendered Surplus:

NIL.

11.0 Reference:

- (i) Railway Board letter No. 2006/Elect(TRS)/441/8 dated 7-10-13.
- (ii) CLW letter No. C-D&D/T/42 dated 20-05-14.

12.0 **Modification Drawing**:

The modified schematics are enclosed at Annexure-IV.

13.0 Agency of Implementation:

CLW, POH workshops and Loco Sheds holding WAP7 type three phase locomotives.

Encl: As above,

(A.K.Goswami) for Director General/Elect.

Copy to:-

Copy to:-	
Secretary (Electric Traction),	For kind
Railway Board,	information
Rail Bhavan, New Delhi-110 001.	please.
1. Chief Electrical Engineer, Chittaranjan Locomotive Works,	For information
Chittaranjan-713 331.	and necessary
2. Chief Works Manager, Electric Loco Workshop, Central Railway,	action please.
Bhusawal-425 201.	
3. Chief Works Manager, Electric Loco Workshop, Eastern Railway,	
Kancharapara, 24 Pargana (N) – 743145 (W.B.)	
4. Chief Works Manager, Loco, Carriage & Wagon Works, Western	
Railway, Dahod, P.O. Freeland Gank – 389160 (Gujrat)	
5. Sr. DEE (TRS), Electric Loco Sheds,	
Central Railway, Ajni (Nagpur)-440008.	
 Central Railway, Kalyan-421304 (Maharashtra) 	
 East Central Railway, Gomoh-828 401 	
Eastern Railway, Howrah-711 106	
 Northern Railway, Ghaziabad (UP)-201 001. 	
 South East Central Railway, BMY Complex, Bhilai, 	
Durg-490 025.	
 North Central Railway, Fazalganj, Kanpur – 208 003 	
 South Central Railway, Lallaguda, Secunderabad – 500 017. 	
 South Eastern Railway, Tatanagar-831 002. 	
 Southern Railway, Royapuram, Chennai-600 013. 	
 West Central Railway, Tughlakabad, New Delhi-110 044. 	
 Western Railway, Vadodara-390 002. 	

(A.K.Goswami) for Director General/Elect

Encl: As above,

REVISED CABLE INDEX FOR MICAS BASED VCU FOR AVOIDING CAB CHANGING FOR WAP7 LOCOS

INPUT REDUNDANCY

S.	Signal Name		T		Cable		FROM			TO		
No		Existing	Redundant processor	Scheme No	Scheme No		Panel	Location	Wago No	То	SUB-D /Connector PIN	
1	AMSB_0101-LBEDemand	HBB-1	STB-1	08C	2521A	0.5 mm	SB-1	XF22S:02	23	411	JD:03	
2	AMSB_0101-LTEDemand	HBB-1	STB-1	08C	2520A	0.5 mm	SB-1	XF22S:02	22	411	JA:02	
3	AMSB_0101-LT/BDem>1/3	HBB-1	STB-1	08C	2522A	0.5 mm	SB-1	XF22S:02	24	411	JD:11	
4	AMSB_0101-LT/BDem>2/3	HBB-1	STB-1	08C	2523A	0.5 mm	SB-1	XF22S:02	25	411	JD:04	
5	AMSB_0101-LPBFaultAck	HBB-1	STB-1	17A	5671A	0.5 mm	SB-1	XF22S:03	04	411	LA:04	
6	AMSB_0101-LBEDemand	HBB-2	STB-2	08D	2521B	0.5 mm	SB-2	XF77S:02	02	412	JA:02	
7	AMSB_0101-LTEDemand	HBB-2	STB-2	08D	2520B	0.5 mm	SB-2	XF77S:01	01	412	JA:01	
8	AMSB_0101-LT/BDem>1/3	HBB-2	STB-2	08D	2522B	0.5 mm	SB-2	XF77S:02	03	412	JD:10	
9	AMSB_0101-LT/BDem>2/3	HBB-2	STB-2	08D	2523B	0.5 mm	SB-2	XF77S:02	04	412	JD:04	
10	AMSB_0101-LPBFAulAckt	HBB-2	HBB-1	17A	5671B	1.5 mm	SB-2	XF77S:03	04	SB-2	XK77V:03-21	
						1.5 mm	SB-2	XK77V:03	21	SB-1	XK22V:03-21	
						1.5 mm	SB-1	XK22V:03	21	SB-1	XF22S:02-51	
						0.5 mm	SB-1	XF22S:02	51	411	OA:01	
11	AMSB_0101-LActKD	STB-1	HBB-1	08A	2500A	0.5 mm	SB-1	XF22S:02	17	411	OA:09	
12	AMSB_0101-LActKD	STB-2	HBB-2	08A	2500B	0.5 mm	SB-2	XF77S:03	20	412	OA:09	
13	AMSB_0101-LSwComprDir	HBB-1	****	06E	3035A	1.5 mm	****	172.2	Q4	SB-2	XK77D-14	
						1.5 mm	SB-2	XK77D	14	SB-2	XF77S:01-49	
						1.5 mm	SB-2	XF77S:01	49	SB-2	XK77V:03-22	
						1.5 mm	SB-2	XK77V:03	22	SB-1	XK22V:03-22	
						0.5 mm	SB-1	XK22V:03	22	SB-1	XF22S:03-28	

Annexure-I/2

14	AMSB_0102-LSwComprOff	HBB-2	STB-1	06E	3034B	1.5 mm	SB-2	XF77S:03	27	SB-2	XK77V:03-18
						1.5 mm	SB-2	XK77V:03	18	SB-1	XK22V:03-18
						1.5 mm	SB-1	XK22V:03	18	SB-1	XF22S:02-48
						0.5 mm	SB-1	XF22S:02	48	411	LA:12
15	AMSB_0102-LSwComprDir	HBB-2	STB-1	06E	3035B	1.5 mm	SB-2	XF77S:03	26	SB-2	XK77V:03-19
						1.5 mm	SB-2	XK77V:03	19	SB-1	XK22V:03-19
						1.5 mm	SB-1	XK22V:03	19	SB-1	XF22S:02-49
						0.5 mm	SB-1	XF22S:02	49	411	LD:12
16	AMSB_0102-MBrakElecOk	HBB-2	STB-1	06H	3008	1.5 mm	SB-2	XF77S:01	17	SB-2	XK77V:03-20
						1.5 mm	SB-2	XK77V:03	20	SB-1	XK22V:03-20
						1.5 mm	SB-1	XK22V:03	20	SB-1	XF22S:02-50
						0.5 mm	SB-1	XF22S:02	50	411	JD:12

OUTPUT REDUNDANCY FOR AVOIDING CAB CHANGING

S.	Signal Name				Cable		FROM				TO
No		Existing processor	Redundant processor	Scheme No	No	Size of cable	Panel	Location	Wago No	То	SUB-D:PIN
1	AMSB_0201-MLampFault	HBB-1	STB-1	17A	2099A	0.5	SB-1	XF22S:02	03	411	JJ:06
2	AMSB_0201-MLampFault	HBB-1	STB-1	17A	5673A	0.5	SB-1	XF22S:03	06	411	JJ:13
3	AMSB_0201-MLampFind	HBB-1	STB-1	17A	5672A	0.5	SB-1	XF22S:03	05	411	JG: 17
4	AMSB_0201-MLampFind	HBB-1	STB-1	17A	2099A	0.5	SB-1	XF22S:02	05	411	JG: 04
5	AMSB_0201-MLampFault	HBB-2	STB-2	17A	2099B	0.5	SB-2	XF77S:03	07	412	JG:03
6	AMSB_0201-MLampFault	HBB-2	STB-2	17A	5673B	0.5	SB-2	XF77S:02	12	412	JG:15
7	AMSB_0201-MLampFind	HBB-2	STB-2	17A	2099B	0.5	SB-2	XF77S:03	80	412	JG:04
8	AMSB_0201-MLampFind	HBB-2	STB-2	17A	5672B	0.5	SB-2	XF77S:03	11	412	JG:17

Annexure-II

REDUNDANCY CONCEPT IMPLEMENTED IN MICAS VCU

	KEDONDA	ISOLATION OF A			
Process	HBB1	HBB2	STB1	STB2	
BEFORE MODIFIC ATION	CAB-1 WILL BE ISOLATED CAB CHANGE NECESSARY	CAB-2 WILL BE ISOLATED CAB CHANGE NECESSARY	CAB-1 WILL BE ISOLATED CAB CHANGE NECESSARY	CAB-2 WILL BE ISOLATED CAB CHANGE NECESSARY	
AFTER MODIFICATION	CAB-1 WILL NOT BE ISOLATED. Normal driving from CAB-1 & CAB-2	CAB-2 WILL NOT BE ISOLATED. Normal driving from CAB-1 & CAB-2	CAB-1 WILL NOT BE ISOLATED. Failure mode active for driving from CAB-1. CAB-1 meters not available.	CAB-2 WILL NOT BE ISOLATED. Failure mode active for driving from CAB-2. CAB-2 meters not available.	
	FAILED FUNCTIONS	FAILED FUNCTIONS	FAILED FUNCTIONS	FAILED FUNCTIONS	
	MCB not monitored Earth Fault Relay	Parking Brake Manual Release Regenerative Brakes not available	Air Dryer Hotel load	Traction MCBs not monitored Over speed 110% & 105%	
NOI	415/110V not monitored Aux. Contact FUSE 415/110V not monitored	Vigilance Control to be isolated manually	Anti spin valve Bg-1	Speedometer alarm output	
-ICATI		Pan-1 not available	Failure mode switch	Earth Fault Relay BUR not monitored	
BEFORE MODIFICATION		Following pressure switches not monitored	Simulation mode switch	Slave (STB2 falls on the slave loco) loco fire alarm on master loco	
FORE		Direct Brake	Bogie cut out switch	Vigilance inputs for buzzer	
BB		Pan-1 & 2 Flow indication Main reservoir – 3 switches Brake feed pipe Brake Cylinder Bg-1 & Bg-2			
AFTER MODIFICATION	SAME AS ABOVE	SAME AS ABOVE	SAME AS ABOVE	SAME AS ABOVE	

Annexure-III

			E	xisting c	ontent in TSD		N	Aodified o	content in TS	D		
SS:13 Cab-	SS No.	Fault No.	Fault Message	Lamp	Effect	Action to be taken by Driver	Fault Message	Lamp	Effect	Action to be taken by Driver		
	SS13	F1301P1	Loco XXX SS13: Cab 1 DISTURBANCE IN PROCESSOR HBB1 Cab 1 may get isolated, drive from cab 2 refer to driver's manual F1301P1	LSFI	Cab-1 may get isolated,	Switch OFF the Electronics and Switch it ON once again. Raise panto, close VCB and resume Traction.	Loco XXX SS13: Cab 1 DISTURBANCE IN PROCESSOR HBB1 "Cab 1 will not isolate, drive from cab 1/2; Press Fault ack. and proceed" F1301P1	LSFI	Cab-1 will not isolate	Cab 1 will not isolate, drive from cab 1 Press Fault acknowledgement button (BPFA) and proceed. Note: MCBs in HB-1 not monitored, Earth Fault relays 415/110, fuse 415/110 not monitored.		
	SS13 F1302P1 Loco XXX SS13: Cab 1 DISTURBANCE IN PROCESSOR STB1 Cab 1 may get isolated, drive from cab 2 refer to driver's manual F1302P1				Cab-1 may get isolated,	Switch OFF the Electronics and Switch it ON once again. Raise panto, close VCB and resume traction.	Loco XXX SS13: Cab 1 DISTURBANCE IN PROCESSOR STB1 "Cab 1 will not isolate, drive from cab 1/2; Press Fault ack. and proceed" F1302P1	LSFI	Cab-1 will not isolate	Cab 1 will not isolate, drive from cab 1. Press Faul acknowledgement buttor (BPFA) and proceed. When Bogie isolation needed Isolate Bogie-1 by MCB 127.1/1, Isolate Bogie-2 by MCB 127.1/2. When MCB OFF required put BL key to OFF position and switch OFF MCB 112.1. Note: Air dryer not working Hotel load not working		
		1		xisting c	ontent in TSD		Modified content in TSD					
SS:14 Cab- 2	SS No.	Fault No.	Fault Message (Existing)	Lamp	Effect (Existing)	Action to be taken by Driver	Fault Message (Modified)	Lamp	Effect (Modified)	Action to be taken by Driver (Modified)		
	SS14	F1401P1	Loco XXX SS14: Cab 2 DISTURBANCE IN PROCESSOR HBB2 Cab 2 may get isolated, drive from cab 1 refer to driver's manual F1401P1	LSFI	Cab-2 may get isolated,	Switch OFF the Electronics and Switch it ON once again. Raise panto, close VCB and resume Traction.	Loco XXX SS14: Cab 2 DISTURBANCE IN PROCESSOR HBB2 "Cab 2 will not isolate, drive from cab 1/2; Press Fault ack. and proceed" F1401P1	LSFI	Cab-2 will not isolate	Cab 2 will not isolate, drive from cab 2. Press Fault acknowledgement button (BPFA); Pan1 not available and isolate vigilance control equipment by switch 237.1(SB-1) put on '0' and proceed. Note: Regenerative brake not working.		
	SS14	F1402P1	Loco XXX SS14: Cab 2 DISTURBANCE IN PROCESSOR STB2 Cab 2 may get isolated, drive from cab 1 refer to driver's manual F1402P1	LSFI	Cab-2 may get isolated,	1. Switch OFF the Electronics and Switch it ON once again. Raise panto, close VCB and resume traction.	Loco XXX SS14: Cab 2 DISTURBANCE IN PROCESSOR STB2 "Cab 2 will not isolate, drive from cab 1/2; Press Fault ack. and proceed" F1402P1	LSFI	Cab-2 will not isolate	Cab 2 will not isolate, drive from cab 2. Press Fault acknowledgement button (BPFA) and proceed. When MCE OFF required put BL key to OFF position and switch OFF MCB 112.1. Note: Following function failed MCB Monitoring (HB-2) Over speed of speedometer, Vigilance warning buzzer and Erath fault auxiliary.		











