

Government of India
Ministry of Railways
Research, Designs & Standards Organisation
Manak Nagar, Lucknow - 226 011
SPECIAL MAINTENANCE INSTRUCTIONS NO. RDSO/ELRS/SMI-145 CRANK
SHAFT FRACTURE OF NO.32 TAP CHANGER

1. OBJECT

Railways have reported cases of Crank Shaft fracture of tap changer ABB make. The probable reasons and remedial measures to overcome above failures are listed in the following enclosed instructions for compliance.

2. INSTRUCTIONS

- i. Instructions for assembling crank shaft with the help of fixture (Annexure-1)
- ii. Maintenance of Crank Shaft in AOH, IOH and POH (Annexure-2)
- iii. Cause effect diagram (Annexure-3)
- iv. Check sheet for Crank shaft breakage (Annexure-4)

3. REFERENCE

- i. M/SABB Instruction No. SWT 5126, SWT 5129 and SWT 5131
- ii. Co-ordination Meeting held on 8.1.1992 at ABB, Baroda.

4. INSTRUCTION DRAWING

Enclosed with instructions

5. APPLICATION TO CLASS OF LOCOMOTIVE

All locomotives fitted with No.32 tap changer of M/S ABB make.

6. AGENCY OF IMPLEMENTATION

Sheds/Shops.

7. PERIODICITY OF IMPLEMENTATION

As per the instructions enclosed.

8. DISTRIBUTION

All Chief Electrical Engineers.



(Arun Srivastava)
Krite Maha Nideshak/Vidyut.

Encl As above

Instruction for making crank shaft assembly to
our drawing AG 106 705 R1

- 1) Degrease the bearing pin-1 and key-2 with a solvent such as trichlorethylene. or white spirit.
- 2) Press the key in the key way of pin sufficiently such that the bearing-3 can be just inserted. (See Fig. 1)




Fig.1

- 3) Fill the bearing with Lithium base grade-3 grease and insert.
- 4) With the key in a vice or press, push it until the ball bearing butts against the race. (See Fig. 2)




Fig.2

- 5) Using the bushing-4, Press ball bearing and key together on to the pin. (See Fig.3)




Fig.3

Ref. HAGT 30454-E

MODIFICATION

REPLACED BY:

REPLACES

DRAWN

CHECKED

APPRD.

AUTHOD.

BBC HINDUSTAN BROWN BOVERI

SwT 5126
sh. 1 of 3

- 6) Make sure the seating diameters $\varnothing 24-r5$ at both ends of bearing pin are clean & free from grease.
- 7) Lightly press the bearing pin in to the half crank shaft-5 untill guidance can be felt. (See Fig. 4)




Fig.4

- 8) Coat the bore $\varnothing 24-H7$ of the half crank shaft with loctite 0601 (joining parts) and press on the bearing pin (See Fig. 4) pressing of bearing pin is to be done with suitable fixture such that load comes on round disc $\varnothing 128$ only (See Fig. 5) and end diameter is guided as per figure.




Fig.5

MODIFICATION:

REPLACED BY:

REPLACES

DRAWN

CHECKED

APPRD.

AUTHOD.

BBC HINDUSTAN BROWN BOVERI ②

SwT 5126
sh. 2 of 3

- 9) Press bearing block-6 on the bearing.
- 10) Press the second half on crank shaft with fixture such that load comes on round disc ϕ 128 only and both end diameters are guided as per figure. (See Fig.6)




Fig.6

MODIFICATION:

REPLACESD BY:

REPLACES:

DRAWN

CHECKED

APPRD.

AUTHOD.

BBC HINDUSTAN BROWN BOVERI

2/2

SwT 5126
sh. 3 of 3

Maintainance of Crank shaft

AoH

- 1) Lubricate connecting Rod bearing area with graphite Lubricating oil.
- 2) Ensure that the fly wheel is not wobbling and not loose. If required change key 6102 or fly wheel 2112
- 3) Check total play between crank pin and connecting rod with bearing liner (2314/2313). If play is more than 0.4 mm change bearing liner 2313.
- 4) Check the tightness of fixing bolts 2107. If they are loose tighten them after ensuring that both ends are equidistants from support. Use medium grade loctite 242 on the bolts to prevent loosening
- 5) Check for any other abnormality.

IoH

- 1) Observe the groove at the crank pins for crank using Die Penetrant test. If crack are observed replace crank shaft.

Rest of the check points as per AoH.

Prepared:	Checked :	Approved :	Maintainance of Crank shaft of Tap changer NO.32	
Without See PL <input type="checkbox"/>	Seq PL No. <input type="checkbox"/>	Seq PL Other No. <input type="checkbox"/>		
Drived from:				
Revision :				
ABB Asea Brown Boverl Ltd.				SwT 5129

PoH

During poH the crank shaft should be Checked for cracks at the crank pin portion. Also looseness of two halves of crank shaft to be checked. If they are found loose key 2101.5 may have to be replaced and assembly to be done as per the guide lines given in instruction SwT 5126..... The end Bearing are to be lubricated with Lithium base grease class 2 If the crank pin diameter is 17.6 mm the crank shaft is to be replaced.

The crank shaft assembly to the base plate is to be done such that the ends of crank shafts are at the same distance from the base of Base plate 1101.


The fixture TC-98 may be used for the purpose

All other points as given for AoH And IoH are to be taken care of.

In case Air Motor with support is to be fitted on different Tap changer procedure for fitment to be followed as per instruction SwT 5130.

The crank shaft should be replaced in 2nd poH.

Prepared:	Checked :	Approved :	Maintainance of Crank shaft of Tap changer NO.32	
Without See PL <input type="checkbox"/>	Seq PL No. <input type="checkbox"/>	Seq PL Other No. <input type="checkbox"/>		
Drived from:				
Revision :				
ABB Asea Brown Boveri Ltd.				SwT 5129



Prepared:	Checked :	Approved :	Maintenance of Crank shaft of Tap changer NO.32	
Without See PL <input type="checkbox"/>	Seq PL No. <input type="checkbox"/>	Seq PL Other No. <input type="checkbox"/>		
Drived from:				
Revision :				
ABB Asea Brown Boveri Ltd.				SwT 5129

For Crank shaft Breakage (Part no. 2101)

Air Motor Sr. No :

Tap changer Sr. No. :

Loco No. / Type :

Date of Commissioning :

Date of Failure :

Whether Line Failure / Shed :

Detection : _____

Details of Failure_ : _____

Shed Investigation Details: _____

Further Details

Whether there is rubbing of
crank shaft rib with the sides
of Base plate Part no. 1101 :

Whether Fixing Bolts Part no.
2107 are loose. :

Whether the Fly wheel is wobbling :

Whether the Fly wheel is loose :

Whether Crank shaft ends are
at equidistance from Base of
Base plate Part no. 1101 :

Prepared:	Checked :	Approved :	Check sheet for Crank Shaft breakage (Part no. 2101) Of tap changer NO.32	
Without See PL <input type="checkbox"/>	Seq PL No. <input type="checkbox"/>	Seq PL Other No. <input type="checkbox"/>		
Drived from:				
Revision :				
ABB Asea Brown Boveri Ltd.				SwT 5131

Base plate Part NO. 1101		:	mm	
Distance of Crank shaft end at Bevel gear side from base of Base plate Part no. 1101				
		:	mm	
Whether Key 1916 properly seated in support 1911				
		:		
Whether support 1911 is broken				
		:		
Whether Hex. bolts 1909 are loose				
		:		
Whether washer 1943 & Bellville washer 1910 provided on bolts 1909				
		:		
Whether Bevel gear Alignment 1926 & 1924 is proper with 50–70% uniform gear meshing				
		:		
Whether there is looseness of crank shaft from the central shaft & key				
		:		
Whether there is excessive play between crank shaft				
		:		
Crank pin & Connecting rod with Bearing liner (2314/2313)		: Play:	I mm	II mm
			III mm	IV mm
Whether Self aligned ball bearing 2103 is defective				
		:		
Whether there is lateral play in Crank shaft				
		:		

Prepared:	Checked :	Approved :	Check sheet for Crank	
Without See PL <input type="checkbox"/>	Seq PL No. <input type="checkbox"/>	Seq PL Other No. <input type="checkbox"/>	Shaft breakage (Part no. 2101)	
Drived from:			Of tap changer NO.32	
Revision :				

ABB Asea Brown Boveri Ltd.

SwT 5131

