## Government of India ( Ministry of Railways ) Research Designs & Standards Organisation Manak Magar, Lucknow-226011 No.EL/3.2.5/J3 MODIFICATION SHEET NO. RDSO/WAM4/169

	1. Tible		
	2. Application	: d.	
	3. Object		Railways have reported failure of inter connectors of TAO 659 traction motor as under :-
		: 1	Failure of inter connectors to negative terminal junction.
	3-2	<b>;</b> .	Failure of bus bar to positive terminal junction.
A MARK TO A	3•3	:	Earth fault on inter connectors between coils below fixing clamps.
	3-4	:	Cracking of leads going to terminal box.
	3•5 .	:	The modification intends to improve the insulation on inter connectors so as to reduce the earth fault cases and minimise failure of bus bar inter connections.
	4. Details of Modification	:	
	4.1	• .	Inter connectors No. 1 to 14 as shown in ALSTHOM'S Drg.No. TR 9016427 may be removed after debrazing.
· }	·\4•2	:	Strip off the insulation covering of inter connectors and clean the surface suitably.
	<b>4.3</b>	:	Carry out the annealing of bare copper inter connectors at temp. 550°C in bright annealing furnace i.e. in the presence of non oxidising atmosphere for four hours.

Carry out the insulation of the inter connectors as :-One layer half lap of Kapton self adhesive tape of size.065 x 20mm.

Three layers half lap as HTV-HET H5-0.5 of M/s. Hitachi er Commiflex EM
Tape size of 0-15 x 20mm. of M/s. Hohmson & Johnson (India)

Stopping final taping by teflou adhesive tape.

- Brazed the inter connectors with respective coils with the help of electric resistance heating using carbon blocks in specially designed brazing tonge.
  - Brazing of connectors with ceils etc. shall be done with silver brazing material INCN Alemand 400 C 80 flux CDA 523 powder or equivalent silver brazing rod, Rupattam foil with suitable flux as presently used.
  - Brazing time one minute maximum under 1200 Amp.
  - Clean the brazed portion properly.
  - Carry out the insulation of brazed portion similar to inter connectors as described above.
  - Final varnishes as usual.
  - Tighten the inter connecting clamp as usual backing position.
  - Baking the complete stator as per existing procedure.
- 5. Schedule of Implementatatation

Check the inter connectors during annual overhaul/repair for any cracks. In case some cracks are observed replace the inter connectors with new one having improved insulation scheme as above. Alternatively improved insulation scheme may be adopted with existing copper connections.

6. Material Required Assistated in Clause 4.4 - 4:

7. Source of Supply

Mrv-HBT H5-0.5 Tape M/s. Hitachi Works of Hitachi Ltd., 3-1-1 Saiwai-Cho, Hitachi-Shi. Ibrakai-Ken, JAPAN

## Connifler EM Tape

M/s. Jhonson & Johnson 9/43, Kirti Nagar, New Delhi- 110015

M/s. Johnson & Johnson, 30, Forjett Street, Bombay- 400 036

Rest material of Clause 4.44 may continue to purchase from the existing supplier of Railways/Production Units.

- tion
- 8. Agency for : i) All Traction Motor/POH Shops.
  Implementa
  - ii) All Blectric Loco Sheds.
  - iii) All loco POH Shops.
  - iv) All Production Units.
- 9. Distributions: As per enclosed list.

DA: As above

( P.K.Jain ) for Director General/Elect: