

भारत सरकार—रल चत्रालय अनुसंधान अभिकल्प और मानक संगठन लखनऊ— 226011

e-mail: dse1rdso@gmail.com Telephone : 0522-2465713 Research, Designs & Standards Organization, LUCKNOW – 226011

Telex: 0535-2424 RDSO-IN

Fax: 91-0522-2452581



Date: 10/09/2018

No. EL/2.2.9/10

 M/s Autometers Alliance limited, C-63, Sector-57

Noida-201 307

2. M/s Medha Servo Drives Pvt Ltd, P-4/5B,IDA Nacharam, Hyderabad-500 076.

**3.** M/s Laxven Systems, Plot No.188/A,Lane –I,Phase – II,Sector –III,IDA Cherapally, Hyderabad-500 051.

**Sub**: Minutes of Meeting at RDSO on 28.08.2018 with OEMs of ESMON for Reliability of "Microprocessor based Electronic speed cum Energy monitoring system for electric locomotives".

Please find enclosed herewith the copy of subject Minutes of Meeting for your information & further necessary action.

(A.K.Shukla)

for Director General Std. / Elect.

Copy to:

Encl: As above

Principal Chief Electrical Engineer, Chittaranjan Locomotive Works, Chittaranjan. 713 331.

Encl: As above

for Director General Std. / Elect.

## Minutes of the meeting at RDSO on 28/08/2018 to review the performance of ESMON for Electric Locomotives

## Present:

RDSO	FIRMS
1. Shri Omprakash Kesari,	1. Shri D.K. Maharana, Product Head,M/s
PEDSE	AAL
2. Shri A.K.Shukla, EDSE/SYS	2.Shri Ankur Tiwari,Assistant Manager,M/s
	AAL
3. Shri G.Meena, SSE/D/Elect.	3.Shri Sumit Wahi,Account Head,M/s AAL
	4.Shri P.B.M. Krishna, Sr. Product Engineer,
	M/s Medha
	5. ShriRavi Kumar ,GM(Marketing), M/s
	Medha
	6.Shri JP Sharma, Manager(Marketing), M/s
	Medha
	7.Shri Ramesh Reddy, Managing Partner, M/s
	Laxven
	8.Shri K.N.Anjaneyulu, Manager Marketing,
	M/s Laxven

A meeting was convened at RDSO to review the performance of ESMON for Electric Locomotives. Thesummary of the discussion are as under:-

- 1. M/s AAL stated that failures of CPU card mainly due to firmware & battery problem. M/s AAL has modified the software to reduce the failure of CPU card. Approval of modification of CPU card has been taken from CLW. Further, firm has supplied the programming kit & firmware to all sheds for implementation. Railways are requested to submit the performance feedback to RDSO. Firm suggested that 3.6V battery should be replaced after 3 years to reduce the failure of CPU cards.
- 2. M/s AAL& M/s Laxven stated that failure of Power Supply card due to capacitors failure. As per firms, capacitors should be replaced after 6
- 3. RDSO advised all the firms to submit detailed investigation report with action plan of Stepper motor failures, PG failures and card failures.
- 4. Railways should plan replacement of unserviceable over aged ESMON equipment as per Railway Board letter no. 98/Elect (G)/138/6, dated 29.05.06 to improve the reliability of ESMON.

5. RDSO advised all the firms to submit chart of energy calibration within a week time to RDSO.

(A K Shukla)

EDSE

Encl: Nil