

भारत सरकार – रेल मंत्रालय अनुसंघान अभिकल्प और मानक संगठन लखनऊ – 226011

e-mail : edse.rdso@gmail.com Telephone : 0522-2465714 Government of India - Ministry of Railways Research, Designs & Standards Organization, LUCKNOW – 226011 Fax: 91-0522-2452581



No. EL/4.2.15/Gen Date: As signed

# **Principal Chief Electrical Engineers,**

- 1. Central Railway, Mumbai CST-400 001
- 2. East Central Railway, Hazipur-844 101
- 3. East Coast Railway, Chandrashekharpur, Bhubaneswar-751 016
- 4. Eastern Railway, Fairlie Place, Kolkata-700 001
- 5. North Central Railway, Subedarganj, Prayagraj-211 033
- 6. Northern Railway, Baroda House, New Delhi-110 001
- 7. North Eastern Railway, Gorakhpur-273001
- 8. North East Frontier Railway, Maligaon, Guwahati-781 011
- 9. North Western Railway, Jaipur-302 006
- 10. South Central Railway, Rail Nilayam, Secunderabad-500 071

- 11. South East Central Railway, Bilaspur- 495 004
- 12. South Eastern Railway, Garden Reach, Kolkata-700 043
- 13. Southern Railway, Park Town, Chennai-600 003
- 14. South Western Railway, Hubli-580 024
- 15. West Central Railway, Jabalpur-482 001
- 16. Western Railway, Churchgate, Mumbai- 400
- 17. Chittaranjan Locomotive Works, Chittaranjan-713 331
- 18. Banaras Locomotive Works, Varanasi 221 004
- 19. Patiala Locomotives Works, Patiala 147 003

# MODIFICATION SHEET NO. RDSO/2024/EL/MS/0498(Rev.0), Dated 02.04.2024

#### 1.0 **TITLE**:

Recording of Flasher light operation either due to fault or manually by Loco Pilot in case of emergency with time stamping in Conventional Electric Locomotives equipped with Microprocessor based control and fault diagnostic system (Ver-3).

# 2.0 BACKGROUND:

- 2.1 Railway Board vide letter No. 2023/Elect(TRS)/440/20 dated 22.12.2023 had advised RDSO that CCRS, in his immediate recommendations pertain to enquiry of Fire accident in Train No. 02570 NDLS-DBG Humsafar Clone express at Sarai Bhopat station of Prayagraj division of NCR at about 17:25hrs on 15.11.2023, has suggested that the "Operation of Flasher light either due to fault or by Loco Pilot in case of emergency shall be recorded with time stamping either through VCD/VCU".
- 2.2 RDSO envisaged the scheme for recording of flasher light operation due to fault or by loco pilot and advised to M/s Medha & Laxven to execute same as proof of concept in conventional locomotive equipped with MPCS (Ver-3). Firms executed the scheme after modification of software in loco no 27738/WAG-7/KZJ & 27429/WAG-7/KZJ on dated 17/2/24 and 18/3/24 respectively. It leads to recording of flasher light operation status either due to fault or due to loco pilot operation in short term as well as in long term data with date and time stamping.


#### 3.0 **OBJECT**:

Recording of Flasher light operation either due to fault or manually by Loco Pilot in case of emergency with time stamping in Conventional Electric Locomotives equipped with MPCS(Ver-3).

#### 4.0 WORKS TO BE CARRIED OUT:

It requires some electrical circuit modification. Run a cable from CAB1 flasher light unit wire no - 801 through Blocking diode and other cable from CAB-2 flasher light unit wire no - 802 through blocking diode to BD board and then connect to MPCS (ver-3) spare input I–127.

# 5.0 **MODIFICATION DRAWING:** The logic circuit used for this modification



#### 6.0 APPLICATION TO CLASS OF LOCOMOTIVES:

Conventional Electric Locomotives equipped with MPCS (ver-3).

#### 7.0 MATERIAL REQUIRED:

- (i) Two Numbers Blocking Diodes.
- (ii) 30 m 2.5 sq. mm Cable with lugs.

#### 8.0 MATERIAL RENDERED SURPLUS:

None

### 9.0 **REFERENCES**:

Railway Board's letter no. 2023/Elect(TRS)/440/20 dated 22.12.2023.

# 10.0 **AGENCY FOR IMPLEMENTATION:**


- (i) Electric Loco Sheds/Diesel Loco Sheds/POH Workshops having Conventional Electric Locomotives equipped with MPCS(Ver-3).
- (ii) OEMs of MPCS require for modified software uploading.

(Sanjay Kumar Tiwari) for Director General/Electrical


Encl.: Annexure Copy to:

As per standard mailing list.

#### **EVENT DATA LOGGED AS**



#### SHORT TERM RECORDED DATA



# LONG TERM RECORDED DATA

Date Minmelyy	Time hlummas	arned .	OHE Voltage	OHE Current Amps	Power Factor	GRÓ	Ctf Brake	Health of Remote Monitoring System	Flasher Light	VCD Status	VCD Cycle	
2:	•	D	0		0 1	0	0	0 1	0	1 0	n	挪
8/03/24	20:05:40	)	0.0	0	. 0.00	ON	OFF	Healthy	OFF	Active	Suppressed	-11
8/03/24	20:05:44	>	0.0	0	0.00	ON	OFF	Healthy	OFF	Active	Soppressed	П
8/03/24	20:05:45	l .	21.7	30	2.00	ON	OFF	Healthy	OFF	Active	Suppressed	- 115
8/03/24	20:06:00	11	26.6	3	50.00	ON	OFF	Healthy	OFF	Active	Suppressed	-11
	20:06:20		26.6	3	56.00	ON	OFF	Healthy	ON	Active	Suppressed	H.
	20:06:40		26.7	3	56.00	ON	OFF	Healthy	ON	Active	Suppressed	TIP.
-	20:07:00	4	26.6	3	56.00	ON	OFF	Healthy	OFF	Active	Suppressed	-11
-	20:07:20	-	25.6	3	70.00	ON	OFF	Healthy	OFF	Active	Suppressed	- IIL
	20:07:40	-	26.6	3	56.00	ON	OFF	Healthy	OFF	Active	Suppressed	F
THE OWNER	20:08:00	-	26.8	2	42.00	DN	OFF	Healthy	OFF	Active	Suppressed	- 11
-	20:08:20		26,8	2	42.00	ON	OFF	Healthy	OFF	Active	Suppressed	IL
	20:08:40	***********	26.7	2	56.00	ON	OFF	Healthy	OFF	Active	Suppressed	IF.
-	20:09:00	-	26.6	3	56.00	ON	OFF	Healthy	OFF	Active	Suppressed	
	20:09:20	-	26.7	3	48.00	DN	OFF	Healthy	OFF	Active	Suppressed	11
rem was	20:09:40		26.6	3	50.00	ON	OFF	Healthy	OFF	Active	Suppressed	
-	20:10:00	-	26.5	3	50.00	ON	OFF	Healthy	OFF	Active	Suppressed	
	20:10:20	1-1-	26.6	3	56.00	ON	OFF	Healthy	OFF	Active	Suppressed	
-	20:10:40	-	26.6	3	42.00	ON	OFF	Healthy	ON	Active	Suppressed	
-	20:10:51	-	26.5	3	36.00	ON	OFF	Healthy	OFF	Active	Suppressed	-
Company Street	20:11:00	Acres de la constante de	26.4		56.00	ON	OFF	Healthy	OFF	Active	Suppressed	168
-	20:11:40	-	26.1	2 2	28.00	DN	OFF	Healthy	OFF	Active	Suppressed	1
CARREST COMPANY	20:12:00	the resemble	26.1		42.00	OH	OFF	Hoalthy	OFF	Active	Suppressed	100
William III		and all and a second	20.2	A PARTY OF THE PAR	42.00	DN	OFF	Healthy	OFF	Active	Suppressed	-