

110-3
MAINTENANCE INSTRUCTION NO. TI/MI/0008

Page <u>1</u> of <u>2</u>	Effective
...2... Pages	From <u>14.9.84</u>

REV. 0

MASTER COPY

GOVERNMENT OF INDIA: MINISTRY OF RAILWAYS
 MANAKNAGAR, LUCKNOW-226011

मूल प्रति

No. ETI/OHE/SE/M/S

Dated 14-9-1984

General Manager (Electrical)
 Central Railway
 Bombay V.T. 400 001

Sub-Failure of 9 tonne insulators.

The Chief Inspector (OHE) was deputed to BSL from 17-7-84 to 18-8-84 to investigate into the cause of failures of 9-tonne insulators in BSL Division. He has reported that at the balance weight anchor locations have not been provided with the double eye distance rods (RI 5183) in BSL Division. It is a serious matter. At higher temperatures, without the double eye distance rods 9-tonne insulators will foul with the tie rods of anti-falling devices provided with the autotension devices. This would be detrimental to the performance of the insulators. This was also brought to the personal notice of Sr. DEE (T&D) BSL, by DD (OHE) - Shri. Arora during the 7th MSG (T&D) meeting held recently at Bombay.

It is requested that urgent action may please be taken to provide the double eye distance rods at the balance weight anchor locations.

Kindly acknowledge receipt.

Encl: Nil.

(K.K. Agarwal) 11.9.84
 for Director General/TI.

Copy to:


1. General Managers (Electrical),
 1. Central Railway, Bombay V.T.-400 001.
 2. Eastern Railway, Fairlie Place, Calcutta-700 001.
 3. Northern Railway, Baroda House, New Delhi-110 001.
 4. Southern Railway, Park Town, Madras-600 003.
 5. South Central Railway, Rail Nilayam, Secunderabad-1
 6. S.E. Railway, Garden Reach, Calcutta-43.
 7. Western Railway, Churchgate, Bombay-400 020.
2. Chief Project Managers; Railway Electrification,
 1. Western Railway, Kota-324 002.
 2. Central Railway, Mathura-281 002.
 3. Post Box No. 77, DM's office building (C.Rly), 2nd Floor, Kings Way Road, Nagpur-440 001.
 4. South Eastern Railway, Ranchi, (BIHAR)-834 001.
 5. Western Railway, Pratap Nagar, Vadodara-390 004.
 6. South Central Railway, Vijayawada (AP)-520 001.

(contd.... P/2)

-2-

3. The Chief Electrical Engineer, Railway Electrification, Southern Railway, Poonamalle High Road, Egmore, Madras-600 008.
4. The Chief Electrical Engineer, Railway Electrification, South Central Railway, Vijayawada (AP)-520 001.
5. Secretary (Electrical), Railway Board, Rail Bhawan, New Delhi.

c/- EEL/OHE/INS/1 file


(K.K. Agarwal)

For Director General/TI.

Encl: Nil.