Telex

: 0535 - 2424 RDSO -IN

Fax

: 91 - 0522 - 2450374

Telephone: 2450374 & 2451200 Telegram: 'RAILMANAK!, Lucknow

: edse@sancharnet.in

: edse@rdso.railnet.gov.in : dell1@rdso.railnet.gov.in



भारत सरकार - रेल मंत्रालय अनुसंधान अभिकल्प और मानक संगठन

लखनऊ - 226011

Government of India - Ministry of Railways Research, Designs & Standards Organization. **LUCKNOW - 226011**

SN10-4440

No. EL/3.1.3

Date: 30 - 07 - 2004

Modification Sheet No. ELRS/MS/0330(Rev. 0)

1.0 Title:

Provision of CTF3 contact in C145 circuit.

2.0 Object:

Railways have reported several cases of burning of ATFEX winding just after changing from Dynamic Braking Mode to Traction Mode. Sometimes C145 contactor remains closed even on Traction Mode because of malfunctioning of its auxiliary N/C interlock on C145 branch, which remains closed.

To eliminate this problem it has been decided to provide N/O interlock of CTF3 (closed in Braking Mode) before the final supply to C145, this ensures that C145 will close in Braking Mode only.

3.0 Work to be carried out:

Connect one CTF3 auxiliary N/O interlock, which is already available as spare, in the circuit of C145 Contactor as shown in enclosed drawing no. SKEL: 4684.

4.0 Application:

All locomotive equipped with Dynamic Braking.

5.0 Material Required:

2.5 mm² Cable – 2 meters (Approx)

6.0 Material rendered surplus:

Nil

7.0 References:

- i. Sr. DEE (TRS), Electric Loco Shed, Kanpur, North Central Railway's Letter No. 230 Elect/TRS/CNB/Tech 56/514 Dated: 01 06 2004.
- ii. Sr. DEE (TRS), Electric Loco Shed, Asansol, Eastern Railway's Letter No. ELS/8/M/N Dated: 22 07 2004
- 8.0 Modification Drawing No.

SKEL: 4684

9.0 Agency for Implementation:

CLW, all POH shops and Electric Loco Sheds

10.0 Distribution:

As per standard mailing list.

DA: RDSO's Drawing No. SKEL: 4684

(Ram Prakash) for Director General (Elect)

