Government of India Ministry of Railways Research, Designs & Standards Organisation Manak Nagar, Lucknow - 226 011

No. EL/3.2.30/CG Dated: 16.3.1984

MODIFICATION SHEET NO. WAM4/136

MODIFIED FLEXIBLE CONNECTION (1623) BETWEEN CGR AND GR OF TAP CHANGER TYPE NO. 32 OF HBB MAKE.

1. OBJECT

Railways have reported many cases of breakages of solid connections provided between switching element (CGR) and Double pole bushing (GR) due to locomotive vibrations. It is proposed to provide a flexible connection in place of solid connection.

2. WORK TO BE CARRIED OUT

Replace the solid connection by flexible connection (SK EL 3726)

3. APPLICATION

Locos fitted with No. 32 tap changer of HBB make.

4. MATERIAL REQUIRED

Flexible connections as per RDSO SK EL 3726 obtainable from M/s HBB, P.B.No. 140. Vadodara 390 001

5. MATERIAL SURPLUS

Existing solid connection - 2 Nos.

6. REFERENCE

- (i) Item (page 8) of the minutes of the meeting held between Railways & M/s HBB in August 83 and minutes circulated vide RDSO letter No. EL/3.2.30/CG dated 24.9.83.
- (ii) M/s HBB Drawing No. TC 96 (Mod A) & TC 97 (Mod B)

7. MODIFICATION DRAWING

RDSO SK EL 3726.

8. <u>AGENCY OF IMPLEMENTATION</u>

All electric loco sheds and POH shops.

HBB/CLW - during manufacture and on tap changers in stock.

9. **DISTRIBUTION**

As per list attached.

K. Vishwakumar

Ihanah an

for Director General (Elec)

Encl: 1.SK EL 3726 2. Mailing list.

