COVERNMENT OF INDIA - MINISTRY OF RAILWAYS RESEARCH, DESIGNS & STANDARDS ORGANISATION

- - 8 - -

or existing localities by Blackino Localitation

No.EL/3.1.3

Manak Nagar, Lucknow. Dated 3-9-1979.

point earthing of power circuit with 28-3P Traction Motor commection

1. Object of modification:

- 1.1 There have been a number of cases of Pailure of insulation to earth on traction motors of WAM4 locomotives. It is considered desirable to reduce the dielectric stress on the motor insulation be earthing the mid-point of the two motors connected in series instead of on one side of the power circuit as at present. In the first instance a modification is to be carried out only on WAM1 locomotives with a permanent 253p connection.
- 1.2 The connection of the mid-points of the motors to the earth will be made through resistors as shown in enclosed sketch No.SK.EL.3176. The resistors are needed to limit the circulating current in the case of a flash-over of any of the motors.

2. Work to be carried out;

- 2.1 Power circuit of the locomotive with permanent 2S-3p connection of traction motors are to be modified as per RDSO sketch SK.RL.3176.
- 3. Application to class of locomotive:
- 3.1 All WAM4 locos having permanent 28-3p connection of traction motors.
- 4. Material required:) As per CLW's instructions and Drg:No.
 5. Material rendered) WAM4 docomotives with BHEL TM165 trac-
- 6. Referencer loss morfost research feelilouff Livid ... (20,000-junia) ... with the Nil Strain and Laborate and the control of the Nil Strain and the control of the contr

- 7. Modification drawings of (assors) delicered loss all. 3 R.D.S.O. SK.EL. 3176 and CIW. Drg. No.CLW.4W.2004.72/A.
 - pluit spectrical magneser (RS); South Seatern Railvay.

- 8. Agency for modificati
- For existing locomotives by Electric Loco Sheds.
- 11) 7: 644 Locos under manufacture by CLW.

(As per list appended below)

and the second s Encl. As above. The second second

for Director General (Elec.)

DISTRIBUTION 2 dories with 2 copies of Drg./Sketch No.SK.EL.3176 to each addressed below:

- 1. Sourctary (Blectric Traction), Redlway Board, Rail Bhavan,

- 2. Chief Electrical Engineers;
 1) Central Railway, Bombay VT-400 CO1.
 11) Northern Railway, Baroda House, New Delhi-110 CO1.
 11) Southern Railway, Park Town-600 CO3.
 10) South Eastern Railway, Garden Reach, Calcutta-700 CO3.
 v) Western Railway, Churchate, Dombay-400 CO3.
 vi) Chittaranjan Locomotive Works, Chittaranjan, Burdwan-713 331.
- 3. Dy.Chief Electrical Engineer Kanchrapara Shops, Eastern Railway, Kanchrapara-743 145
- 4. Dy.Chief Blectrical Engineer (POH), Elect. Loco POH Shops, Central Railway, Bhusaval-425 201.
- 5. Sr. Divisional Electrical Engineers (TRS), Electric Loco Sheds,
 i) Northern Railway, Kanpun 208 001.
 ii) South Eastern Railway, Tatanagar-831 002.
 iii) South Eastern Railway, Bhilai-490 001.
- 6. Divil. Electrical Engineers (TRS), Electric Loco Sheds,
 .i) Northern Railway, Ghazlabed 201 001.
 ii) Western Railway, Barode 330 002.
 iii) Central Railway, Bhusaval 125 301.
- 7. Divil. Electrical Engineers, Traction Motor Shops,
 1) Fazalganj, Kanpur-208 DOI.
 11) South Eastern Railway, Tatanagar-831 002:
- 8. Dy.Director Inspection (Slect.), RDS0, Chittaranjan Locomotive Works, Chittaranjan, Disti Burdwan-713 331,
 9. Dy.Chief Electrical Engineer (Works), Nouth Eastern Railway, Tatanagar-831 OCC.
 10. Divil. Electrical Engineer (RS), South Eastern Railway, Waltairs, N.P.



