



भारत सरकार - रेल मंत्रालय
अनुसंधान अभिकल्प और मानक संगठन
लखनऊ - 226 011
EPBX (0522) 2451200
Fax (0522) 2450679

Government of India-Ministry of Railways
Research Designs & Standards Organisation
Lucknow - 226 011
DID (0522) 2450115
DID (0522) 2465310



No. SV.AS.Trelleborg

Dated: 17.12.2018

Genera Manager (Mechanical/Store)

1. Central Railway, CSTM, Mumbai - 400 001
2. Eastern Railway, Fairly Place, Kolkata- 700 001
3. Northern Railway, Baroda House, New Delhi-110 001
4. Southern Railway, Park Town, Chennai - 600 003
5. South Central Railway, Secunderabad-500 071
6. South Eastern Railway, Garden Reach, Kolkata-700 043
7. North Eastern Railway, Gorakhpur-273 001
8. North East Frontier Railway, Maligaon, Guwahati- 781 011
9. Western Railway, Churchgate, Mumbai-400020
10. East Central Railway, Hazipur-844 101
11. East Coast Railway, Railway Complex, Bhubaneswar- 751 023
12. North Central Railway, Allahabad-211 001
13. North Western Railway, Jaipur-302 006
14. South Western Railway, Hubli- 580023
15. West Central Railway, Jabalpur- 482 001
16. South East Central Railway, Bilaspur- 495 004
17. Konkan Railway Corporation Ltd., Corporate office, Belapur Bhawan, Navi Mumbai – 400 614
18. BEML, Bangalore Complex New, Post Box No. 7501, Bangalore - 560075
19. Integral Coach Factory, Chennai - 600038
20. Rail Coach Factory, Kapurthala – 144 602
21. Modern Coach Factory, Rae Bareli – 229212

Sub: Temporary delisting of M/s Ashika Commercial Pvt. Ltd., Plot no. F221-223 RIICO Industrial Area, Phase – 1, Silora, Kishangarh, Rajasthan for Air Spring (140 KN Capacity)

- Ref:**
- 1) MCF/RBL Letter no. M-400/MCF/RBL/Bogie Plg/K-025, dated 14.10.2018.
 - 2) Central Railway letter no. BB.M.LTT.Component failure, dated 16.10.2018.
 - 3) M/s Ashika letter no. ACPL/RDSO/140 KN Air Spring/CP/18-19/237 dated 25.11.2018.

Vide letters under reference, MCF and Central Railway informed about significant number of failures of air bellows in air springs (140 KN capacity) supplied by M/s Ashika Commercial Pvt. Ltd. (OEM: M/s Trelleborg, UK).


Since air spring is safety item, such type of poor quality products can not be allowed to proliferate in Railways. Further, the firm has also accepted that there were some lapses at their end during manufacturing of air bellows.

It has been decided to Temporary Delist the firm for air springs of 140 KN capacity, with following details for a period until compliance of non-conformities are advised by vendor and same are verified by RDSO.

S. No.	Specification no.	Firm's name	Address	Status of registration
1	STR C-K 509 (Rev. 2, Amendment no. 4 of October 2016) for Air spring (140 KN capacity) for Mainline/ Rajdhani ICF coaches fitted with ICF type bogie and LHB coaches fitted with FIAT type bogie. S no 82 at page number 80 in RDSO vendor directory valid from 1-7-2018 to 31-12-2018.	M/s Ashika Commercial Pvt. Ltd.	Works address: Plot no. F221-223 RIICO Industrial Area, Phase – 1, Silora, Kishangarh, Rajasthan Office Address: 1, Garstin Place, 4C Orbit, Kolkata – 700001	Temporary Delisted

This has been issued with the approval of competent authority.

DA: Nil


 (Shobhit Pratap Singh)
 Dy. Director/Carriage
 for Director General/Carriage

Copy to:

- 1) DME/Chg., Rail Bhawan, Railway Board, New Delhi – 110 001- for kind information.
- 2) ED/QA/Mech/RDSO, Lucknow – for kind information and necessary action please.
- 3) M/s Ashika Commercial Pvt. Ltd., 1, Garstin Place, 4C Orbit, Kolkata – 700001.
- 4) MR/ISO Cell/RDSO, in ref. to para 4.2.2.3 of ISO Doc. No. QO-D-8.1-11 Ver 1.0.